

**Design Services for US-41 Reconstruction from East of MacInnes Dr to Isle Royal St.-  
Houghton QA2**

**Requisition #2752**

Q: Under consultant's responsibilities, it does not mention anything about performing Geotechnical Investigation, PPMS Task 3510, and Conducting Drainage Study, PPMS Task 3522, yet both are checked on sheet 9 of the RFQ. Please clarify.

A: The geotechnical investigation and drainage study are not included. PPMS tasks 3510 and 3522 should be unchecked.